

### **Aiken County School District Cyclic Maintenance**

### Summer Report 2015



We would like to thank the principals and the administrative staff for allowing the contractors to work within the schools and for the cooperation given in allowing access to the facilities.

> Bill Williams, WCI Group LLC Lucille Bradley, WCI Group LLC

1711 Wood Creek Farms Road, Suite B Elgin, SC 29045 803-708-0592 wci.group@aol.com



### **TABLE OF CONTENTS**

PROJECT	LOCATION	PAGE
ABATEMENT		3
	<b>Belvedere Elementary</b>	4-5
	Millbrook Elementary	6-7
FLOORING		8
	<b>Belvedere Elementary</b>	9-10
	Chukker Creek Elementary	11-12
	East Aiken Elementary	13-14
	Millbrook Elementary	15-16
	South Aiken High	17-18
<b>GYM FLOORS</b>		19
	Middle Schools	20
	Jefferson Elementary RSM Elementary	21
	High Schools	22
	High School cont.	23
HVAC		24
	Aiken Elementary	25
	North Augusta Elementary	26




### **TABLE OF CONTENTS**

PROJECT	LOCATION	PAGE
PAINTING		27
	Aiken Middle	28
	Millbrook Elementary	29
	Mossy Creek Elementary	30-31
	New Ellenton Middle	32-33
	Redcliffe Elementary	34
ROOFING		35
	Belvedere Elementary	36
	Byrd Learning Center	37
	Millbrook Elementary	38



## ABATEMENT







Scope of Project: Removal of all asbestos flooring and residue

Provided Below is a summary of work performed:

Done	BELVEDERE ELEMENTARY SCHOOL
✓	Protection and containment of areas to be abated
~	Removal of all cove base, VCT, carpet or adhesive that contain asbestos
✓	Clean up of abated areas
~	Clean air clearances



### ABATEMENT @ MEDIA CENTER



### **BELVEDERE ELEMENTARY SCHOOL**



ABATEMENT @ CLASSROOM





### Scope of Project: Removal of all asbestos flooring and residue

Provided Below is a summary of work performed:

Done	MILLBROOK ELEMENTARY SCHOOL
✓	Protection and containment of areas to be abated
~	Removal of all cove base, VCT, carpet or adhesive that contain asbestos
✓	Clean up of abated areas
~	Clean air clearances



### HEAT MACHINE REMOVING TILE IN CLASSROOM



MILLBROOK ELEMENTARY SCHOOL



ABATEMENT @ CLASSROOM



## FLOORING



### **CARPET TILE** and **VINYL COMPOSITE TILE**








Scope of Project: Prepping and installation of new vct and carpet

Provided Below is a summary of work performed:

Done	BELVEDERE ELEMENTARY SCHOOL	
~	Removal and storage of furniture	
~	Prepared surface for new carpet or VCT flooring and trim out with cove base	
$\checkmark$	VCT areas stripped, sealed, and waxed	
~	Furniture relocated	



### VINYL COMPOSITE TILE INSTALLATION @ CORRIDORS



**BELVEDERE ELEMENTARY SCHOOL** 



CARPET TILES INSTALLATION @ MEDIA





## Scope of Project: Remove existing flooring, prep and install new VCT, cove base and accessories

Provided below is a summary of work that has been performed:

Done	CHUKKER CREEK ELEMENTARY SCHOOL
✓	Removed existing flooring
~	Prepared surface for new VCT, floored, trimmed out with cove base and accessories
~	VCT areas stripped, sealed, and waxed



### PREPPING OF SUBGRADE IN CORRIDOR



### CHUKKER CREEK ELEMENTARY



### INSTALLATION OF VINYL COMPOSITE TILE @ CORRIDOR





Scope of Project: Remove existing flooring, prep and install new carpet, vinyl composite tile, cove base and accessories.

Provided below is a summary of work that has been performed:

Done	EAST AIKEN ELEMENTARY SCHOOL
✓	Removal of furniture
✓	Removed existing flooring
~	Prepared surface for new carpet or VCT/trimmed out with cover base accessories
~	VCT areas stripped, sealed, and furniture relocated
$\checkmark$	Relocate furniture



### CHORUS ROOM FLOORING PREP




### EAST AIKEN ELEMENTARY SCHOOL



CHORUS ROOM FLOORING COMPLETED





Scope of Project: Remove existing flooring, prep and install new VCT/Carpet, cove base and accessories

Provided below is a summary of work that has been performed:

Done	MILLBROOK ELEMENTARY SCHOOL	
✓	Removal of furniture	
~	Prepared surface for new carpet or VCT/trimmed out with cover base accessories	
✓	VCT areas sealed	
<b>√</b>	Relocate furniture	



### CARPET @ CLASSROOM



### MILLBROOK ELEMENTARY SCHOOL



VINYL COMPOSITE TILE @ CLASSROOM





Scope of Project: Prep and install new VCT/Carpet, cover base and accessories.

Provided below is a summary of work that has been performed:

Done	SOUTH AIKEN HIGH SCHOOL
$\checkmark$	Removal of furniture
<b>√</b>	Removed existing flooring
~	Prepared surface for new carpet or VCT/trimmed out with cove base and accessories
~	VCT areas stripped, sealed, and furniture relocated
$\checkmark$	Relocate furniture



### AUDITORIUM (BEFORE)



South Aiken High School



AUDITORIUM (AFTER)



# **GYM FLOOR**



### **Scrubbing and Coating**



AIKEN MIDDLE SCHOOL

A. L. CORBETT MIDDLE SCHOOL

**KENNEDY MIDDLE SCHOOL** 

JACKSON MIDDLE SCHOOL

### LEAVELLE McCAMPBELL MIDDLE SCHOOL

NEW ELLENTON MIDDLE

NORTH AUGUSTA MIDDLE SCHOOL

PAUL KNOX MIDDLE SCHOOL

SCHOEFIELD MIDDLE SCHOOL

Scope of Project: Scrubbing and coating of wooden gymnasium floors.

Done	MIDDLE SCHOOLS	
✓	Clean gym floor thouroughly sweep and vacuum	
✓	Remove all surface soil, debris, sand, and grit	
✓	Mechanically scrubb/ buff and application of one coat of finish	





### JEFFERSON ELEMENTARY

### **RSM ELEMENTARY**

### Scope of Project: Scrubbing and coating of wooden gymnasium floors.

Provided below is a summary of work that has been performed:

Done	ELEMENTARY SCHOOLS
~	Clean gym floor thouroughly sweep and vacuum
~	Remove all surface soil, debris, sand, and grit
~	Mechanically scrubb/ buff, and application of one coat of finish



**AIKEN HIGH SCHOOL** 

### MIDLAND VALLEY HIGH SCHOOL

### \*NORTH AUGUSTA HIGH SCHOOL\*

**RSM HIGH SCHOOL** 

SOUTH AIKEN HIGH SCHOOL

### SILVER BLUFF HIGH SCHOOL

### WAGENER SALLEY HIGH SCHOOL

\*North Augusta High to receive Scrubbing and Coating over Thanksgiving break\*





Scope of Project: Scrubbing and coating of wooden gymnasium floors.

Provided below is a summary of work that has been performed:

Done	HIGH SCHOOLS
~	Clean gym floor thouroughly sweep and vacuum
~	Remove all surface soil, debris, sand, and grit
~	Mechanically scrubb/ buff, and application of one coat of finish



## HVAC



### AIKEN ELEMENTARY

### NORTH AUGUSTA ELEMENTARY

Done	SUMMARY OF WORK PERFORMED
$\checkmark$	Demolition of existing HVAC systems
$\checkmark$	Renovation and construction of areas to receive new HVAC system
$\checkmark$	MEP and Fire sprinkler system installation
$\checkmark$	Testing and balancing of system



### DEMOLITION OF EXISTING ABOVE CEILING



AIKEN ELEMENTARY SCHOOL



DUCT INSTALLATION AND SEALING OF DUCT



### FINALIZING OF MULTIPLE TRADE WORK ABOVE CEILING



### NORTH AUGUSTA ELEMENTARY



INSTALLATION AND SECURING OF COOLING TOWER



## PAINTING



**AIKEN MIDDLE** 

### MILLBROOK ELEMENTARY

### MOSSY CREEK ELEMENTARY

### **NEW ELLENTON MIDDLE**

### **REDCLIFFE ELEMENTARY**

Done	SUMMARY OF WORK PERFORMED
$\checkmark$	Cleaned, prepped, and primed surfaces to receive paint
✓	Application of one coat of waterborne apoxy @ cmu walls
~	Priming and coating of all metal doors, apply industrial enamel finish coat
$\checkmark$	Light sanding of all wood doors and one coat of urethane



### PAINTING OF SIGNAGE , STUCCO, AND COLUMNS




AIKEN MIDDLE SCHOOL



PAINTING OF CAFETERIA AND STAGE AREA



### PAINTING OF WALLS AND WAINSCOTING



### MILLBROOK ELEMENTARY SCHOOL



PAINTING OF SCHOOL SIGNAGE





**MOSSY CREEK ELEMENTARY SCHOOL** 



PAINTED ENTRANCE



### ACCENT ENTRANCE TO CLASSROOMS




### **MOSSY CREEK ELEMENTARY**




PAINTING OF ALL STRUCTURES AND CEILING





### FINISHED PAINTED DUCT AND ACCENT BAND





### REMOVAL OF MOISTURE @ DAMAGED WALL



PREPPING AND PRIMING OF MOISTURE DAMAGED WALL



### **NEW ELLENTON MIDDLE SCHOOL**



FINISHED PAINT OF MOISTURE DAMAGED WALL







### **REDCLIFFE ELEMENTARY SCHOOL**



PAINTING OF CORRIDOR



# Roofing



**Belvedere Elementary** 

**Byrd Learning Center** 

**Millbrook Elementary School** 

Done	SUMMARY OF WORK PERFORMED
$\checkmark$	Tear off existing roof
✓	Installation of layers of roof insulation
✓	Installation of roof membrane, flashing and curbs



### HOT MOPPING @ ROOF



**Belvedere Roofing** 





### INSTALLATION OF STANDING SEAM ROOF



Byrd Learning Center



BUILT UP ROOF



### INSTALLATION OF ROOFING BOARD



### MILLBROOK ELEMENTARY GYM







### ADDRESSING THE NEEDS OF INDIVIDUAL CLIENTS AND PROVIDING THE BEST COMBINATION OF QUALITY, EFFICIENCY & ECONOMY

On a number of occasions, you have gone above and beyond what one could expect in meeting challenges and obstacles for our program... I appreciate your candor, knowledge and follow through. –Todd Webber, Charlotte-Mecklenburg Schools

My experience with Bill goes back almost 20 years... [his] presence reassures us of a quality building/project regardless of the general contractor awarded the job. --Kevin Chipman, Director of Construction Facilities, Aiken County Schools

I've come to truly rely on what Bill tells me. He's proven himself to be a straight shooter. When we need information, service or other assistance to solve a challenge confronting us, Bill can be depended on to provide a solution or influence others to respond as appropriate.
-- Melinda Anderson, Board Chairperson, Richland County District 2 School Board